



**RECALL NOTICE REGARDING
WHISPER-DRY™ AIRMOVER (Model #2300)**

December 19, 2009

MODEL: Mytee Products, Inc. model #2300 Whisper-Dry™ Airmover, manufacturing dates June 2009 through December 2009.

REASON FOR RECALL: Motor may overheat, resulting in a fire hazard.

PHOTO/DRAWING OF THE PRODUCT:



RECALL INSTRUCTIONS: UNPLUG THIS PRODUCT. DO NOT CONTINUE TO USE THIS PRODUCT. Immediately return this product to Mytee Products, Inc., for repair/modification at no cost. You may contact Mytee Products, Inc. and Mytee Products, Inc. will arrange to pick this product up from you.

REPAIR: You should not attempt to repair this product.